
foamyiQ[®]

BRACKET MOUNTING INSTRUCTIONS



CLEAN area and **MEASURE**.



INSTALL coverplate on bracket.



REMOVE tape. **PRESS** bracket to surface. **ALLOW** 24 hours to cure.



MARK and DRILL top and bottom holes.



PLACE anchors and **MOUNT** using top and bottom screws.



ATTACH cartridge.



When depleted, **UNLOCK** the cartridge, **RECYCLE** and **REPLACE** with a fresh new cartridge.

